

Dear NMS/SRINIR

Sanction No. SS4/R/107195 dated 28/03/2023 has been generated in reference to Service order No. 398262 dated 23/03/2023.

Area : SS4 COIMBATORE

Model : 52141501SD02602/RD EDGESX 236C 33 TDI FL WN

Replacement Product Code : 52141501SD02602 RD EDGESX 236C 33 TDI FL WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02602 RD EDGESX 236C 33 TDI FL WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220702602DR00479

Invoice No : 11107766

Invoice Date : 03/03/2023

DOP : 03/03/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Customer_Expectations_-_Not_allowing_Repairs

Job Code Desc : RELAY#OVERLOAD PROTECTOR BURNT#PRIMARY TRANSIT DAMAGE

PRA submitted by : AVUDAIAPPAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : Kannan Kannan

Address : Kannan Kannan Malakovil pirivu Pollachi Subdistri

City: A.Nagore B.O

Telephone Number :

Mobile Number : 8489231633

Observation text: EVAPORATOR GAS LEAK - DEFECTIVE FLIPKART DENIED REPLACEMENT
T DOP- 05-03-2023

Approval remark: EVAPORATOR LEAK - CUST CASE ECOM

Sanction text: Evaporator Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.