## Dear NMS/SRINIR

Sanction No. SS4/A/100922 dated 15/11/2023 has been generated in reference to Service order No. 612766 dated 23/10/2023.

Area: SS4 COIMBATORE

Model: 40101701SD01226/EI 18PINV4R32-WWP

Replacement Product Code: 40101701SD01226 EI 18PINV4R32-WWP

 ${\tt Product\ Category\ :\ AIR\ CONDITIONER}$ 

Defective Product Code: 40101701SD01226 EI 18PINV4R32-WWP

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230401226SA05494

Invoice No : 11283779
Invoice Date : 11/06/2023

DOP : 11/06/2023

DEALER / CUSTOMER : CUSTOMER
Damage/Defective : Defective

AC UNIT : IDU-ODU

ODU No : 230401226SA05808

Nature Of Problem : Customer\_Expectations\_-\_Not\_allowing\_Repairs

Job Code Desc : CONTROL CARD#ODU - MAIN/CONTROL PCB NOT WORKING#APPLIANCE TO B

E REPLACED

PRA submitted by : Marudhudurai R Customer / Dealer Code : 40000E

Customer / Dealer Name : Lenin Prabakaran A Lenin Prabakaran A

Address: Lenin Prabakaran A Lenin Prabakaran A 476 A Veeramamunivar Nagar,

Pudukkudi Ma

City: Sengipatti

Telephone Number: 9094328659 Mobile Number: 9094328659

Observation text: E6 Error - ODU PCB faulty-11-6-23 cust not allowing to rep

air appliance to be replaced

Approval remark: ODU PCB DEFECT-CUST CASE-DOP 11/6/23. CUST NOT ACCEPTING RE

PAIR

Sanction text: Approved as a special case

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective servic e executive.