

Dear KHANGAN/ADHI

Sanction No. SS4/R/108666 dated 07/02/2024 has been generated in reference to Service order No. 369233 dated 17/01/2024.

Area : SS4 COIMBATORE

Model : 2MUBIF/RD EDGEPRO 210CT 5.2INDIGOFLOR

Replacement Product Code : 2MUBIF RD EDGEPRO 210CT 5.2INDIGOFLOR

***** Replacement from Category Stock *****

Defective Product Code : 2MUBIF RD EDGEPRO 210CT 5.2INDIGOFLOR

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 1608820514

Invoice No :

Invoice Date :

DOP : 30/03/2017

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Customer_Expectations_-_Not_allowing_Repairs

Job Code Desc : CABINET#RF BASE DEFECTIVE / DAMAG#PRIMARY TRANSIT DAMAGE

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : INDHIRANI INDHIRANI

Address : INDHIRANI INDHIRANI 3/3080-1,ATHAMNAGAR, PATTINAMK PATTINAMKATTAN
RAMNAD-

City: RAMANATHAPURAM H.O

Telephone Number : 9003432538

Mobile Number : 9751120645

Observation text: Door rusty- spare not available HO approval attached Category stock to be replaced

Approval remark: MAIN DOOR RUSTY - SPARE NOT AVL APPROVED BY HO

Sanction text: Sanctioned as per HO approval Category machine replacement

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.