

Dear KHANGAN/ADHI

Sanction No. SS4/A/101017 dated 23/04/2024 has been generated in reference to Service order No. 853274 dated 22/04/2024.

Area : SS4 COIMBATORE

Model : 40101701SD00997/GIC 18TTC3-RVB SPLIT

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD00997 GIC 18TTC3-RVB SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220400997SA01304

Invoice No : 11034707

Invoice Date : 29/04/2022

DOP : 29/04/2022

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Melvyn Joshua

Customer / Dealer Code : 40000E

Customer / Dealer Name : AIR CONTROL ENGINEER AIR CONTROL ENGINEER

Address : AIR CONTROL ENGINEER AIR CONTROL ENGINEER 1/7, THIRUVIDAI MURUTHUR
ROAD ULLUR KOMBAKONAM

City: KOMBAKONAM

Telephone Number : 9944534393

Mobile Number : 9788505743

Observation text: IDU and UDO PCB problem sales return note (Nonsalable condition) Date of purchased 22 APRIL 2024

Approval remark: IDU AND ODU PCB DEFECT CUST CASE

Sanction text: approved as a special case

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.