

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101379 dated 14/12/2024 has been generated in reference to Service order No. 723349 dated 10/12/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01061/DSS 18TI3R32-RWA SPLIT

Replacement Product Code : 40101701SD01442 SIC 18TTC3 WYQ SPLIT

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01061 DSS 18TI3R32-RWA SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 231001061SA00079

Invoice No : 11005694

Invoice Date : 27/10/2023

DOP : 27/10/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

AC UNIT : IDU-ODU

ODU No : 231001061SA00559

Nature Of Problem : Dealer\_replaced\_to\_customer\_approved\_by\_Service

Job Code Desc : SEALED SYSTEM#GAS LEAK#APPLIANCE TO BE REPLACED

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : EVARIST ENGINEERING EVARIST ENGINEERING

Address : EVARIST ENGINEERING EVARIST ENGINEERING NO 209, NAMMANDHAN ROAD

ARISIPALAYAM

City: Arisipalayam

Telephone Number : 9442184853

Mobile Number : 9442184853

Observation text: CUSTOMER CASE-DEALER REPLACED TO CUSTOMER SEALED SYSTEM GA

S LEAK. CUS DOP-04/03/2024, PLEASE APPROVE THE SAME FOR REPLACEMENT SIR

Approval remark: GAS LEAK - CUST CASE- NOT ACCEPTING REPAIR. REPLACED THRU D  
EALER.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.