

Dear NMS/SRINIR

Sanction No. SS4/R/106723 dated 28/11/2022 has been generated in reference to Service order No. 360249 dated 22/11/2022.

Area : SS4 COIMBATORE

Model : 52141501SD01641/R D EPRO 205 TAF 3.2 GLS BLU

Replacement Product Code : 52141501SD01641 R D EPRO 205 TAF 3.2 GLS BLU

\*\*\*\*\* Replacement from Category Stock \*\*\*\*\*

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD01641 R D EPRO 205 TAF 3.2 GLS BLU

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 190701641DR12410

Invoice No : na

Invoice Date : 31/07/2019

DOP : 12/10/2019

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Fire/\_/Burnt\_Case

Job Code Desc : EXTERNAL FACTORS#FIRE - EXTERNAL FACTOR#APPLIANCE TO BE REPLAC ED

PRA submitted by : MAHADEVAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : SURESH SURESH

Address : SURESH SURESH NO;1/268 ;; EAST STREET ;; KOVILPAPPAKUDI ;; LM;

NEAR MARIE KOVIL ;; PODUMBU ;; MADURAI ;;

City: Podumbu B.O

Telephone Number : 6379615540

Mobile Number : 9865334741

Observation text: FOUND FIRE CASE - APPROVED BY MR.ROHIT DOP : 12-10-2019 DE FECTIVE CAT STOCK APPROVED BY HO

Approval remark: FIRE CASE- APPROVED BY HO. TO BE REPLACED FROM CAT STOC K.

Sanction text: approved as per Rohit mail Category stock replacement

Kindly take necessary action.

SRINIR

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.