

Dear NMS/SRINIR

Sanction No. SS4/R/106840 dated 27/12/2022 has been generated in reference to Service order No. 368563 dated 20/12/2022.

Area : SS4 COIMBATORE

Model : 52141501SD02545/RD EDGE 215C 33 TAI FL BL

Replacement Product Code : 52141501SD02545 RD EDGE 215C 33 TAI FL BL

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02545 RD EDGE 215C 33 TAI FL BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220602545DR01071

Invoice No : 11109863

Invoice Date : 21/09/2022

DOP : 21/09/2022

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

Nature Of Problem : Dealer_Expectations_-_Not_allowing_Repairs

Job Code Desc : VERY HOT DOOR SURFACE (GRILL)

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SRI KAMACHI ELECTRONICS SRI KAMACHI ELECTRONICS

Address : SRI KAMACHI ELECTRONICS SRI KAMACHI ELECTRONICS ;NO:5/347/4 SALEM
BYPASS ROAD HARUR NNMAHAL OPPOSITE

City: Harur S.O

Telephone Number : 9688463842

Mobile Number : 9443634778

Observation text: DEALER STOCKSET COMPLAINT SEALED SYSTEM GAS LEAK CAPILLARY
JOINT AND DEALER WANT REPLACEMENT ONLY FOR THE SAME PLEASE APPROVE THE SA
ME SIR

Approval remark: GAS LEAK-DEALER STOCK SET CASE.

Sanction text: Sealed system problem in the machine

Kindly take necessary action.

SRINIR

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.