

Dear NMS/SRINIR

Sanction No. SS4/R/106931 dated 20/01/2023 has been generated in reference to Service order No. 376289 dated 12/01/2023.

Area : SS4 COIMBATORE

Model : 52141501SD01871/RT EONASTRA 285B 25 HI OX BL

Replacement Product Code : 52141501SD01871 RT EONASTRA 285B 25 HI OX BL

***** Replacement from Category Stock *****

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD01871 RT EONASTRA 285B 25 HI OX BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 201101871FR00113

Invoice No : 11067199

Invoice Date : 16/12/2020

DOP : 09/01/2021

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Functional_Defect_-_Not_repairable

Job Code Desc : SEALED SYSTEM#GAS LEAK -CONDENSOR_DISCHARGE OUTLET JOINT#APPLIANCE TO BE REPLACED

PRA submitted by : MAHADEVAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : ABIBULLA ABIBULLA

Address : ABIBULLA ABIBULLA IYARAJ KOVIL ST : TENKASI,, TIRUNELVELI

City: TENKASI H O

Telephone Number : 9894049090

Mobile Number : 9894049090

Observation text: FOUND INTERNAL GAS LEAK CUSTOMER NOT ACCEPTING FOR REPAIR

CUSTOMER DOP : 09-01-2021 DEFECTIVE

Approval remark: INTERNAL GAS LEAK CASE. approved by HO as a special case.

AMC AMOUNT TO BE COLLECTED AGAINST REPLACEMENT.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

SRINIR

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.