

Dear NMS/SRINIR

Sanction No. SS4/R/107118 dated 05/03/2023 has been generated in reference to Service order No. 391044 dated 28/02/2023.

Area : SS4 COIMBATORE

Model : 52141501SD01812/RT EONVIBE 346B 25 HCIT ST RH

Replacement Product Code : 52141501SD01812 RT EONVIBE 346B 25 HCIT ST RH

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD01812 RT EONVIBE 346B 25 HCIT ST RH

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220101812FR00578

Invoice No : 11003918

Invoice Date : 14/02/2022

DOP : 14/02/2022

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

Nature Of Problem : Dealer_replaced_to_customer_approved_by_Service

Job Code Desc : SEALED SYSTEM#GAS LEAK - UNABLE TO IDENTIFY#APPLIANCE TO BE REPLACED

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : KANNAN AC SPARES KANNAN AC SPARES

Address : KANNAN AC SPARES KANNAN AC SPARES NO : 25 , PARA MATHI MAIN ROAD STREET , PUDUR , OPPOSITE PRIYA TOWER , NAMAKKAL POST AND DISTRICT - 637001

City: NAMAKKAL H O

Telephone Number : 9489566724

Mobile Number : 9443003724

Observation text: CUSTOMER CASE,DEALER REPLACED TO CUSTOMER.SEALED SYSTEM GAS LEAK.CUS DOP- 07/02/2023. PLEASE APPRV THE SAME FOR REPLACEMENT SIR

Approval remark: GAS LEAK-CUST CASE-NEW MACHINE. REPLACED THRU DEALER.

Sanction text: Sealed system problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.