

Dear NMS/SRINIR

Sanction No. SS4/A/100626 dated 13/03/2023 has been generated in reference to Service order No. 391063 dated 13/03/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01217/DSS 18II5R32 WWR

Replacement Product Code : 40101701SD01217 DSS 18II5R32 WWR

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01217 DSS 18II5R32 WWR

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 221201217SA00041

Invoice No : 16047522

Invoice Date : 10/03/2023

DOP : 10/03/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

AC UNIT : IDU-ODU

ODU No : 221201217SA00012

Nature Of Problem : Dealer_Expectations_-_Not_allowing_Repairs

Job Code Desc : PRODUCT PACKING#BOTTOM THERMOCOL#ESTIMATE GIVEN

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : M1 MARKETING M1 MARKETING

Address : M1 MARKETING M1 MARKETING NO 23, VCM STREET OPPOSITE TO BUS STAN
D TIRUPATTUR

City: Tirupattur H.O

Telephone Number : 79228651

Mobile Number : 9443686127

Observation text: NEW MACHINE DEFECTIVE COMPLAINT.SEADLED SYSTEM GAS LEAK IN
THE UNIT DEALER WANT REPLACEMENT ONLY FOR THE SAME PLEASE APPROVE SIR

Approval remark: GAS LEAK-DEALER STOCK SET CASE.

Sanction text: GAS LEAK-DEALER STOCK SET CASE.

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.