

Dear NMS/SRINIR

Sanction No. SS4/A/100662 dated 30/04/2023 has been generated in reference to Service order No. 396870 dated 22/04/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01250/EI 18TINV3R32 WWC

***** Refund *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01250 EI 18TINV3R32 WWC

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230301250SA00218

Invoice No : FAC3R92400007647

Invoice Date : 11/04/2023

DOP : 11/04/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : Rajkumar Rajkumar

Address : Rajkumar Rajkumar No.1, Om shakthi nagar, varichikudy

City: Kottuchery S.O

Telephone Number :

Mobile Number : 9600459846

Observation text: ODU PCB issue - ECOM purchase Customer not allowing to repair-10-4-23 SRN updated - No stock

Approval remark: ODU PCB DEFECT-CUST CASE- DOP 10/4/2023. CUST NOT ACCEPTING REPAIR.

Sanction text: PCB problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.