

Settlement of Claim

Dear Ramesh Ramesh,(8883939555)

Chennai,Tamil nadu

Greeting from Team Bridgestone!

We thank you for trusting us with your tyre requirements and appreciate your patience during the inspection of your product.

After conducting the inspection of your tyre, please find the observations made by our technical expert:

Customer ID	1297728	
Complaint Ref. No.	W0242888	
Date of Inspection	12/05/2023	
Vehicle Make & Model	Chevrolet	Tavera
Reg. No & Consumed Mileage	TN82Z0497	
Fitment	REP	
Tyre Size & Pattern	205/65R15	B390
Dealer Name	Sri Abirami Tyres And Wheel Care	Chennai,Tamil Nadu
Serial No & Dot Code	4W9LCEJ3022	
Name	Sri Abirami tyres and wheel care & D Naresh [Qualified Expert in the inspection of tyre]	

Damage observation : Sidewall Cut

Damage description: A localized rupture on the sidewall area.

Damage analysis: When the sidewall portion of the tyre gets hit by some sharp and hard external object, the sidewall rubber gets cut.

1. Impact with an external object
2. Damage by kerb or pothole
3. Misapplication
4. Wrong tyre or rim size selection
5. Improper inflation or overloading may aggravate the damage.
6. Failure may occur at or after the time of impact.

Conclusion :

We are settling your claim under our unconditional warranty policy in line with our aim to keep our customers happy and satisfied. We will be offering you a new tyre at a special price of Rs. 3084 for the damage caused.

Warranty Policy Guide

We value the trust you have placed in our products and services and would like to thank you for your feedback that helps us improve our offerings.

In case of any further clarification, please feel free to reach out to us.

Toll Free No: 1800-266-8055

Email: grievance-officer@bridgestone.co.in

Or visit <https://www.bridgestone.co.in/en/customer-care/contact-us>

Best Regards,

Customer Care Bridgestone India

Damage Photo	DOT Photo	Additional 1	Additional 2
View	View		

Additional 3	Additional 4	Additional 5	Additional 6

Clearance policy: Please ensure that you claim your product within 21 days of receipt of this report.

Registered Office: Bridgestone India Private Limited, Address: Ploat A43, Phase II, MIDC Chakan, Village
Sawardari, Tel - Khed, Dist - Pune, Maharashtra 410501 OR visit: <https://www.bridgestone.co.in>