

Dear NMS/SRINIR

Sanction No. SS4/R/107416 dated 27/05/2023 has been generated in reference to Service order No. 416269 dated 16/05/2023.

Area : SS4 COIMBATORE

Model : 52141501SD01870/RT EON 275B 25 HI TH ST

Replacement Product Code : 52141501SD01870 RT EON 275B 25 HI TH ST

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD01870 RT EON 275B 25 HI TH ST

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220601870FR00119

Invoice No : 11103619

Invoice Date : 11/07/2022

DOP : 11/07/2022

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Customer_Expectations_-_Not_allowing_Repairs

Job Code Desc : WATER LEAKAGE/SWEATING#SWEATING - CABINET EXTERNAL#APPLIANCE T O BE REPLACED

PRA submitted by : AVUDAIAPPAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : MANJULA DEVI.V

Address : MANJULA DEVI.V NO.76 RAMAR KOVIL STREET MANNUR, RAMANADHAPURAM, POLLACHI, COIMBATORE

City: Polachi R S

Telephone Number : 9788667101

Mobile Number : 9585213171

Observation text: DEFECTIVE CABINET EXTERNAL LEAK CUSTOMER NOT ALLOWING REPAIRS DOP 11.07.2022

Approval remark: CABINET EXTERNAL LEAK/SWEATING. TRAINERS RECOMMENDATION FOLLOWED. CUST CASE- DOP 11/7/2022.

Sanction text: Cabinet leakage in the machine

Kindly take necessary action.
GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.