

Dear NMS/SRINIR

Sanction No. SS4/R/107417 dated 27/05/2023 has been generated in reference to Service order No. 418602 dated 23/05/2023.

Area : SS4 COIMBATORE

Model : 52141501SD01870/RT EON 275B 25 HI TH ST

Replacement Product Code : 52141501SD01870 RT EON 275B 25 HI TH ST

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD01870 RT EON 275B 25 HI TH ST

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 221201870FR00989

Invoice No : 11118174

Invoice Date : 07/03/2023

DOP : 21/01/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Functional_Defect_-_Not_repairable

Job Code Desc : WATER LEAKAGE/SWEATING#SWEATING - ON TABLE TOP#APPLIANCE TO BE REPLACED

PRA submitted by : MAHADEVAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : M.MUTHU KUMAR M.MUTHU KUMAR

Address : M.MUTHU KUMAR M.MUTHU KUMAR NO 183, THILLANKULAM, NILAVILAKKU LEFT SIDE, TUTICORIN

City: Achankulam B.O

Telephone Number : 9037383671

Mobile Number : 9037383671

Observation text: FOUND SWEATING IN THE EXTERNAL CABINET REPAIR NOT POSSIBLE
DEFECTIVE TRAINER INFORMED CUSTOMER DOP : 21-01-2023

Approval remark: SWEATING CASE- MOHAN ADVISE IMPLEMENTED-CUST CASE DOP JAN 2023

Sanction text: Sweating problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.