

Dear NMS/SRINIR

Sanction No. SS4/A/100743 dated 12/06/2023 has been generated in reference to Service order No. 403009 dated 08/06/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01126/SIC 18TTC3-WWA Split

Replacement Product Code : 40101701SD01127 SIC 18TTC3-WWB SPLIT

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01126 SIC 18TTC3-WWA Split

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230301126SA02078

Invoice No : 11015883

Invoice Date : 05/04/2023

DOP : 05/04/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

AC UNIT : IDU-ODU

ODU No : 230301126SA03614

Nature Of Problem : Functional_Defect_-_Not_repairable

Job Code Desc : PRODUCT PACKING#CARTON TORN#ESTIMATE GIVEN

PRA submitted by : MAHADEVAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : MAGESHWARI RAJA SEGAR MAGESHWARI RAJA SEGAR

Address : MAGESHWARI RAJA SEGAR MAGESHWARI RAJA SEGAR NO 483\2 GOLDEN NAGAR
THENPATHU SOUND

City: Tirunelveli Town

Telephone Number : 9629378924

Mobile Number : 9629378924

Observation text: FOUND GAS LEAK AT THE CUSTOMER PLACE CUSTOMER NOT ACCEPTI
NG FOR REPAIR CUSTOMER DOP : 05-04-2023 ALT MODEL

Approval remark: GAS LEAK - CUST CASE-NEW MACHINE. CUST NOT ACCEPTING REPAIR

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than abo
ve sanction no. stands void.

- If any alteration required in above details than this document needs to be
regenerated (pdf format) through smartnet system. Contact respective servic
e executive.