

Dear NMS/SRINIR

Sanction No. SS4/A/100760 dated 15/06/2023 has been generated in reference to Service order No. 403602 dated 14/06/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01228/SIC 24ITC3-WWA SPLIT 3S

Replacement Product Code : 40101701SD01228 SIC 24ITC3-WWA SPLIT 3S

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01228 SIC 24ITC3-WWA SPLIT 3S

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230200001SA00827

Invoice No : 11124021

Invoice Date : 12/06/2023

DOP : 12/06/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

AC UNIT : IDU-ODU

ODU No : 230200001OD01374

Nature Of Problem : Dead\_on\_Arrival

Job Code Desc : PRODUCT PACKING#BOTTOM THERMOCOL#ESTIMATE GIVEN

PRA submitted by : MAHADEVAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : NASIMA BEGAM NASIMA BEGAM

Address : NASIMA BEGAM NASIMA BEGAM NATHERSHA STREET , BEGAMPUR POST , DI  
NDIGUL ,

City: Begampur

Telephone Number : 9551997253

Mobile Number : 9551997253

Observation text: FOUND GAS LEAK AT THE CUSTOMER PLACE - DOA CASE CUSTOMER NOT ACCEPTING FOR REPAIR CUSTOMER DOP : 12-06-2023 DEFECTIVE

Approval remark: GAS LEAK AT THE TIME OF INSTALLATION. CUST NOT ACCEPTING REPAIR.

Sanction text: GAS LEAKED FOUND AT THE TIME OF INSTALLATION. CUST NOT ACCEPTING REPAIR.

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.