

Dear NMS/SRINIR

Sanction No. SS4/A/100758 dated 14/06/2023 has been generated in reference to Service order No. 403287 dated 11/06/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01140/SIC 18DTC3-WWA SPLIT

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01140 SIC 18DTC3-WWA SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230401140SA01275

Invoice No : 11125632

Invoice Date : 17/04/2023

DOP : 17/04/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : GIRIAS INVESTMENT PVT LIMITED GIRIAS INVESTMENT PV

Address : GIRIAS INVESTMENT PVT LIMITED GIRIAS INVESTMENT PVT LIMITED NO 214 /10 SARADHA COLLEGE ROAD NEAR FAIR LAND ROAD SALEM

City: Fair Lands

Telephone Number : 8939970355

Mobile Number : 8939970354

Observation text: CUSTOMER CASE. ODU PCB DEFECT AND CUSTOMER NOT ALLOWED TO REPAIR FURTHER. DEALER REPLACED TO CUSTOMER.CUS DOP-22/04/2023.

Approval remark: ODU PCB DEFECT-CUST CASE-DOP 22/4/2023 REPLACED THRU DEALER

Sanction text: PCB problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.