

Dear NMS/SRINIR

Sanction No. SS4/A/100751 dated 14/06/2023 has been generated in reference to Service order No. 402550 dated 05/06/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01126/SIC 18TTC3-WWA Split

Replacement Product Code : 40101701SD01127 SIC 18TTC3-WWB SPLIT

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01126 SIC 18TTC3-WWA Split

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 221001126SA06873

Invoice No : 00

Invoice Date : 12/04/2023

DOP : 12/04/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

AC UNIT : IDU-ODU

ODU No : 221201126SA00775

Nature Of Problem : Functional_Defect_-_Not_repairable

Job Code Desc : PRODUCT PACKING#BOTTOM THERMOCOL#ESTIMATE GIVEN

PRA submitted by : MAHADEVAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : RANANDHAN RANANDHAN

Address : RANANDHAN RANANDHAN NO 292-A CHINNA SURAIKAIPATTI STREET

City: Ambalapuli Bazaar

Telephone Number :

Mobile Number : 9842689073

Observation text: FOUND GAS LEAK AT THE CUSTOMER PLACE CUSTOMER NOT ACCEPTING FOR REPAIR CUSTOMER DOP : 12-04-2023 DEFECTIVE

Approval remark: GAS LEAK - CUST CASE- DOP 12/4/2023

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.