

Dear NMS/SRINIR

Sanction No. SS4/R/107483 dated 14/06/2023 has been generated in reference to Service order No. 409620 dated 26/04/2023.

Area : SS4 COIMBATORE

Model : 52141501SD01583/R T EON VALOR 290P 3.4 COS BLU

Replacement Product Code : 52141501SD01583 R T EON VALOR 290P 3.4 COS BLU

***** Replacement from Category Stock *****

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD01583 R T EON VALOR 290P 3.4 COS BLU

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 191101583FR00216

Invoice No : 14091170009320

Invoice Date : 11/08/2020

DOP : 11/08/2020

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Functional_Defect_-_Not_repairable

Job Code Desc : SEALED SYSTEM#GAS LEAK -CONDENSOR_DISCHARGE OUTLET JOINT#APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : T NILAVATHI T NILAVATHI

Address : T NILAVATHI T NILAVATHI NO: 348, SENKARAI VELLANKUDI; KILAPADIKA I POST, PERUNKUDI

City: Pulivalam S.O

Telephone Number : 6382658704

Mobile Number : 7806984569

Observation text: Gas leak in condenser- 11-8-20 Non repairable -cust agreed for Cat stock Vasanth escalation case-HO Approval attached

Approval remark: GAS LEAK-CONDENSER LEAK-NON REPAIRABLE. CATEGORY STOCK APPROVED- HO

Sanction text: Category machine approval received for replacement

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.