

Dear NMS/SRINIR/ajayes

Sanction No. SS4/W/101820 dated 27/06/2023 has been generated in reference to Service order No. 428710 dated 20/06/2023.

Area : SS4 COIMBATORE

Model : 52141601SD00282/WTEON ALR 75 5.0 FISGS ROGR

Replacement Product Code : 52141601SD00282 WTEON ALR 75 5.0 FISGS ROGR

Product Category : WASHING MACHINE

Defective Product Code : 52141601SD00282 WTEON ALR 75 5.0 FISGS ROGR

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230400282FW00196

Invoice No : 11128246

Invoice Date : 03/06/2023

DOP : 03/06/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : Cabinet

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 600 Labour Rs. 300 (Includes gas charging , if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - PAINT SCRATCHED#APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VEMBU SONS ELECTRONICS VEMBU SONS ELECTRONICS

Address : VEMBU SONS ELECTRONICS VEMBU SONS ELECTRONICS NO 49; MADURAI ROAD; CONTONMENT ; TRICHY;

City: Bheema Nagar

Telephone Number : 9865458282

Mobile Number : 9865458282

Observation text: Cabinet damaged in washer Top 150 dealer policy - Carton box attached Appliance to be replaced

Approval remark: CABINET DAMAGED -TRANSIT/HANDLING DAMAGES.

Sanction text: Top 150 dealer damaged policy case

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.