

Dear NMS/SRINIR

Sanction No. SS4/A/100769 dated 23/06/2023 has been generated in reference to Service order No. 402721 dated 06/06/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01251/SFC 18LTC3-WWR SPLIT

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01251 SFC 18LTC3-WWR SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230201251SA00004

Invoice No : 11005198

Invoice Date : 23/05/2023

DOP : 23/05/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : NATURAL AIRCON SOLUTION NATURAL AIRCON SOLUTION

Address : NATURAL AIRCON SOLUTION NATURAL AIRCON SOLUTION 87/2, NEAR APOLLO

MEDICAL ARANTAGI PUTHUKOTTAI ROAD

City: Arantagi

Telephone Number : 9626949234

Mobile Number : 9626949234

Observation text: Main PCB defect Dealer not allowing to repair SRN updated - No stock

Approval remark: MAIN PCB DEFECT-DEALER STOCK SET CASE.

Sanction text: PCB problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.