

Dear NMS/SRINIR

Sanction No. SS4/A/100799 dated 04/07/2023 has been generated in reference to Service order No. 404781 dated 29/06/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01254/SIC 12TTC3-WWA SPLIT 3S

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01254 SIC 12TTC3-WWA SPLIT 3S

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230500008SA06572

Invoice No : 11127888

Invoice Date : 27/05/2023

DOP : 27/05/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : GIRIYAS INVESTMENT PVT LTD GIRIYAS INVESTMENT PVT

Address : GIRIYAS INVESTMENT PVT LTD GIRIYAS INVESTMENT PVT LTD NO 469, SEK KALAI ROAD, NEAR PERIYAR SELAI KARAIKUDU, SIVAGANGA,

City: Karaikudi H O

Telephone Number : 8939517222

Mobile Number : 8939516222

Observation text: IDU and ODU PCB issue-17-6-23 Dealer replaced to customer on approval SRN updated - No stock

Approval remark: IDU/ODU PCB DEFECT-CUST CASE- DOP 17/6/23 REPLACED THRU DEALER.

Sanction text: Dealer defective case

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.