

Dear NMS/SRINIR/ajayes

Sanction No. SS4/R/107660 dated 26/07/2023 has been generated in reference to Service order No. 436619 dated 15/07/2023.

Area : SS4 COIMBATORE

Model : 52141501SD02575/RD EDGEPRO 255C 33 TAI MN WN

Replacement Product Code : 52141501SD02575 RD EDGEPRO 255C 33 TAI MN WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02575 RD EDGEPRO 255C 33 TAI MN WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 221202575DR00433

Invoice No : 11130602

Invoice Date : 07/07/2023

DOP : 07/07/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : TopLidOrCover,

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 600 Labour Rs. 300 (Includes gas charging , if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - TABLE TOP#APPLIAN
CE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VEMBU ELECTRONIC

Address : VEMBU ELECTRONIC 49 MADURAI ROAD ; SANTHOMAND ; BHEEMA NAGAR T
IRUCHIRAPPALLI

City: BHEEMA NAGAR

Telephone Number : 9865458282

Mobile Number : 9865458282

Observation text: Side panel bottom damaged Top 150 dealer policy -EBO Ap
pliance to be replaced

Approval remark: CABINET DAMAGED FROM THE BASE-TRANSIT/HANDLING DAMAGES.

Sanction text: Top 150 dealer damaged policy case

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.