

Dear NMS/SRINIR

Sanction No. SS4/W/101861 dated 03/08/2023 has been generated in reference to Service order No. 437231 dated 17/07/2023.

Area : SS4 COIMBATORE

Model : 52141601SD00418/WTEON VLVT 70 5.0 FDTN MTBK

Replacement Product Code : 52141601SD00418 WTEON VLVT 70 5.0 FDTN MTBK

Product Category : WASHING MACHINE

Defective Product Code : 52141601SD00418 WTEON VLVT 70 5.0 FDTN MTBK

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230600418FW00054

Invoice No : 11129454

Invoice Date : 19/06/2023

DOP : 19/06/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

Nature Of Problem : Dealer_replaced_to_customer_approved_by_Service

Job Code Desc : CONTROL CARD#NO WATER INTAKE#ADJUSTED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & CO VASANTH & CO

Address : VASANTH & CO VASANTH & CO SHRI SEVAGAN ANNAMALAI CHETTI RKS ; NO:
240/2 SEKKALAI ROAD KARAIKUDI

City: Karaikudi Southstreet S.O

Telephone Number : 9940112574

Mobile Number : 9940112574

Observation text: PCB issue at time of demo-6-7-23 Dealer replaced to customer on approval Appliance to be replaced

Approval remark: PCB DEFECT DURING DEMO-CUST CASE REPLACED THRU DEALER.

Sanction text: PCB problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.