

Dear NMS/SRINIR/ajayes

Sanction No. SS4/R/107730 dated 08/08/2023 has been generated in reference to Service order No. 312545 dated 02/08/2023.

Area : SS4 COIMBATORE

Model : 52141501SD02858/RD EMARVEL 207B THF LQ WN

Replacement Product Code : 52141501SD02858 RD EMARVEL 207B THF LQ WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02858 RD EMARVEL 207B THF LQ WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230502858DR04217

Invoice No : 11130046

Invoice Date : 27/06/2023

DOP : 27/06/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : SidePanel

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 500 Labour Rs. 200 (Includes gas charging , if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL REAR BOTTOM BUKCLING#APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & CO VASANTH & CO

Address : VASANTH & CO VASANTH & CO NO 4/1;161;6 AND 1617, MURARI TOWER; M ATTA GOPURAM, KUMBESWARAN SOUTH ST

City: KOMBAKONAM

Telephone Number : 2421555

Mobile Number : 8838729965

Observation text: Side panel Dent Top 150 dealer policy Appliance to be replaced

Approval remark: SIDE PANEL DENT-TRANSIT/HANDLING DAMAGES.

Sanction text: Top 150 dealer damaged policy case

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.