

Dear NMS/SRINIR/ajayes

Sanction No. SS4/R/107773 dated 17/08/2023 has been generated in reference to Service order No. 315384 dated 09/08/2023.

Area : SS4 COIMBATORE

Model : 52141501SD02364/RD CHAMP 114B 23 EWI MG WN

Replacement Product Code : 52141501SD02364 RD CHAMP 114B 23 EWI MG WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02364 RD CHAMP 114B 23 EWI MG WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 221202364DR00127

Invoice No : 11130600

Invoice Date : 07/07/2023

DOP : 07/07/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : SidePanel,TopLidOrCover

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 500 Labour Rs. 300 (Includes gas charging , if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - TABLE TOP#APPLIAN
CE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VEMBU SONS ELECTRONICS VEMBU SONS ELECTRONICS

Address : VEMBU SONS ELECTRONICS VEMBU SONS ELECTRONICS NO 49; MADURAI ROAD;
CONTONMENT ; TRICHY;

City: Bheema Nagar

Telephone Number : 9865458282

Mobile Number : 9865458282

Observation text: TABLE TOP AND SIDE PANEL DENT Top 150 dealer policy -EBO

Appliance to be replaced

Approval remark: CABINET DAMAGED -TRANSIT/HANDLING DAMAGES.

Sanction text: Top 150 dealer damaged policy case

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.