

Dear NMS/SRINIR/ajayes

Sanction No. SS4/R/107800 dated 28/08/2023 has been generated in reference to Service order No. 315720 dated 10/08/2023.

Area : SS4 COIMBATORE

Model : 52141501SD02947/RT EONVIBE 366B HCIT MT BK

Replacement Product Code : 52141501SD02947 RT EONVIBE 366B HCIT MT BK

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02947 RT EONVIBE 366B HCIT MT BK

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230602947FR00868

Invoice No : 11130333

Invoice Date : 04/07/2023

DOP : 04/07/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : SidePanel

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 600 Labour Rs. 200 (Includes gas charging , if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL DENT# APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SATHIYA AGENCIES SATHIYA AGENCIES

Address : SATHIYA AGENCIES SATHIYA AGENCIES SOUTH KAR ST, POST OFFICE ROAD TIRUPATTUR SIVAGANGA

City: Tirupattur S.O

Telephone Number : 8870474985

Mobile Number : 8870474985

Observation text: Side panel Dent Top 150 dealer policy Appliance to be replaced

Approval remark: FF- SIDE PANEL DENT- NOT REPAIRABLE.

Sanction text: Top 150 dealer damaged policy case

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.