

Dear NMS/SRINIR

Sanction No. SS4/A/100773 dated 23/06/2023 has been generated in reference to Service order No. 403567 dated 14/06/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01216/SIC 18ITC5-WWR

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01216 SIC 18ITC5-WWR

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230401216SA01671

Invoice No : 16048539

Invoice Date : 21/04/2023

DOP : 21/04/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SRI MEERA REFRIGERATIONS SRI MEERA REFRIGERATIONS

Address : SRI MEERA REFRIGERATIONS SRI MEERA REFRIGERATIONS no- 19 thanthai periyar nagar 2nd street, burma colony, KARAIKKUDI-6300 02, TAMIL NADU, IN

City: Karaikudi Southstreet S.O

Telephone Number : 9942127268

Mobile Number : 9942127268

Observation text: Gas leak in ODU condensor-30-5-23 Dealer replaced to customer on approval SRN updated - No stock

Approval remark: GAS LEAK - CUST CASE-NEW MACHINE. REPLACED THRU DEALER.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.