

Dear NMS/SRINIR

Sanction No. SS4/A/100868 dated 19/09/2023 has been generated in reference to Service order No. 409194 dated 29/08/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01251/SFC 18LTC3-WWR SPLIT

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01251 SFC 18LTC3-WWR SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230201251SA02638

Invoice No : 11128149

Invoice Date : 31/05/2023

DOP : 31/05/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SAMU ELECTRONICS SAMU ELECTRONICS

Address : SAMU ELECTRONICS SAMU ELECTRONICS NO:12, SARANGABANI SANNATHI STREET, KOMBAKONAM

City: Kombakonam

Telephone Number : 9345968198

Mobile Number : 9500240862

Observation text: ODU - Damaged-wrongly updated as defect Non repairable

SRN updated - No stock

Approval remark: ODU DAMAGED-TRANSIT/HANDLING DAMAGES. ASP HAS WRONGLY UPDATED AS DEFECTIVE NOT REPAIRABLE.

Sanction text: Approved as a special case

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.