

Dear NMS/SRINIR

Sanction No. SS4/A/100867 dated 19/09/2023 has been generated in reference to Service order No. 409413 dated 31/08/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01153/SIC 12TTC5-WWA SPLIT 5S

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01153 SIC 12TTC5-WWA SPLIT 5S

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230201153SA00270

Invoice No : 11124630

Invoice Date : 28/03/2023

DOP : 28/03/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SRI LAKSHMI FURNITURE

Address : SRI LAKSHMI FURNITURE 220A BIG BAZAAR STREET MANNARGUDI

City: Kumbakonam Bazar S.O

Telephone Number : 6381420512

Mobile Number : 6381420512

Observation text: Gas leak in ODU condensor-1-6-23 Dealer replaced to customer on approval SRN updated - No stock

Approval remark: GAS LEAK - CUST CASE-NEW MACHINE. REPLACED THRU DEALER.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.