

Dear NMS/SRINIR

Sanction No. SS4/R/108077 dated 31/10/2023 has been generated in reference to Service order No. 338798 dated 25/10/2023.

Area : SS4 COIMBATORE

Model : 52141501SD02575/RD EDGEPRO 255C 33 TAI MN WN

***** SRN *****

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02575 RD EDGEPRO 255C 33 TAI MN WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 221102575DR00363

Invoice No : 11136119

Invoice Date : 29/09/2023

DOP : 29/09/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : AVUDAIAPPAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : MGB ELECTRONICS MGB ELECTRONICS

Address : MGB ELECTRONICS MGB ELECTRONICS NO:7 , MUNISPAL OFFICE ROAD, TIRU

PUR 9524632151

City: Tirupur H.O

Telephone Number : 9524632151

Mobile Number : 9524632151

Observation text: SIDE PANEL DENT BOTTOM BUCKLING NOT REPAIRABLE DEALER WANT

S REPLACEMENT DOP 29.09.2023 SRN DUE TO STOCK UNAVAILABILITY

Approval remark: SIDE PANEL DENT AND BOTTOM BUCKLING. NOT FEASIBLE TO REPAIR

.

Sanction text: dealer damaged case

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.