

Dear NMS/SRINIR

Sanction No. SS4/A/100917 dated 02/11/2023 has been generated in reference to Service order No. 612773 dated 23/10/2023.

Area : SS4 COIMBATORE

Model : 40101701SD00044/GSC 12 FG 6 ROG FV HARMONY RED

Replacement Product Code : 40101701SD00044 GSC 12 FG 6 ROG FV HARMONY RED

***** Replacement from Category Stock *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD00044 GSC 12 FG 6 ROG FV HARMONY RED

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 180400044SA00260

Invoice No : 00095

Invoice Date : 12/04/2019

DOP : 12/04/2019

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

AC UNIT : IDU-ODU

ODU No : 180400044SA00326

Nature Of Problem : Fire/_Burnt_Case

Job Code Desc : EVAPORATOR - ALUMINIUM#DAMAGED#APPLIANCE TO BE REPLACED

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VIJAY KUMAR

Address : VIJAY KUMAR NO25 AVVAINAGAR NEW 4/220 THIRUPATHUR VELLORE TIRUPATTUR H.O

City: Tirupattur H.O

Telephone Number : 9994503566

Mobile Number : 9742398945

Observation text: FIRE CASE, Mr. ROHIT APPROVAL HAS BEEN ATTACHED. PLEASE APPROVE SIR

Approval remark: FIRE CASE- APPROVED BY HO.

Sanction text: Burnt case and Rohit Rohit approval Attached for Category machine replacement

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.