

Dear NMS/SRINIR/ajayes

Sanction No. SS4/R/108345 dated 15/12/2023 has been generated in reference to Service order No. 356120 dated 08/12/2023.

Area : SS4 COIMBATORE

Model : 52141501SD03178/RD EDGEPRO 255C TAF MN WN

Replacement Product Code : 52141501SD03178 RD EDGEPRO 255C TAF MN WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03178 RD EDGEPRO 255C TAF MN WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 231103178DR00186

Invoice No : 11138994

Invoice Date : 07/12/2023

DOP : 07/12/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : SidePanel

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 500 Labour Rs. 100 (Includes gas charging , if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL REAR BOTTOM BUCKLING#APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VEMBU SONS ELECTRONICS VEMBU SONS ELECTRONICS

Address : VEMBU SONS ELECTRONICS VEMBU SONS ELECTRONICS NO 49; MADURAI ROAD; CONTONMENT ; TRICHY;

City: Bheema Nagar

Telephone Number : 9865458282

Mobile Number : 9865458282

Observation text: Side panel bottom damaged Top 150 dealer policy -Marne insurance case Appliance to be replaced

Approval remark: CABINET DAMAGED FROM THE BASE-TRANSIT/HANDLING side panel buckling. NOT FEASIBLE TO REPAIR

Sanction text: Top 150 dealer damaged case

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.