

Dear NMS/SRINIR

Sanction No. SS4/R/108393 dated 26/12/2023 has been generated in reference to Service order No. 357541 dated 13/12/2023.

Area : SS4 COIMBATORE

Model : 52141501SD01914/RD EDGEPRO 205C 33 TAF ZN BL

Replacement Product Code : 52141501SD01937 RD EDGEPRO 205C 33 TAF RZ WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD01914 RD EDGEPRO 205C 33 TAF ZN BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220501914DR02055

Invoice No : 0

Invoice Date : 12/01/2023

DOP : 12/01/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Functional_Defect_-_Not_repairable

Job Code Desc : WATER LEAKAGE/SWEATING#SWEATING - ON TABLE TOP#APPLIANCE TO BE REPLACED

PRA submitted by : Kumaraselvan R

Customer / Dealer Code : 40000E

Customer / Dealer Name : UMARANI UMARANI

Address : UMARANI UMARANI MADURAI SOUTH SANDHIYA HOSPITAL NEAR MADURAI

City: Arasaradi H O

Telephone Number : 9025918289

Mobile Number : 9025918289

Observation text: Table top sweating, cust not allowed for repair Pls appr r eplacement from FG, Stk avl Cust DOP: 12.01.23

Approval remark: SWEATING-CUST NOT ACCEPTING REPAIR.

Sanction text: Approved as a special case alt model confirmed by customer

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.