

Dear NMS/SRINIR

Sanction No. SS4/R/108291 dated 02/12/2023 has been generated in reference to Service order No. 354254 dated 02/12/2023.

Area : SS4 COIMBATORE

Model : 2NWQIF/RD EDGEPRO240CT5.2 INDIGO FLRT

Replacement Product Code : 2NWQIF RD EDGEPRO240CT5.2 INDIGO FLRT

***** Replacement from Category Stock *****

Defective Product Code : 2NWQIF RD EDGEPRO240CT5.2 INDIGO FLRT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 1606820173

Invoice No :

Invoice Date :

DOP : 22/03/2017

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Social_Media_/_Top_Management

Job Code Desc : CABINET#RF BASE DEFECTIVE / DAMAG#PRIMARY TRANSIT DAMAGE

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SRIRAMAN SRIRAMAN

Address : SRIRAMAN SRIRAMAN NO; 53/26 MELA IRANDHAM ST MANNARAGUID

City: Kumbakonam Bazar

Telephone Number : 9788044729

Mobile Number : 9043239943

Observation text: Main door rusty - Zendesk case HO approval attached Category stock to be replaced

Approval remark: main door rusted- to be replaced from cat stock approved by HO

Sanction text: Sanctioned as per Rohit mail for Category machine replacement

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.