

Dear KHANGAN/SRINIR/ajayes

Sanction No. SS4/W/102054 dated 22/01/2024 has been generated in reference to Service order No. 367444 dated 11/01/2024.

Area : SS4 COIMBATORE

Model : 52141601SD00395/WSAXIS DX 70 5.0 SN2 T ROBL

Replacement Product Code : 52141601SD00395 WSAXIS DX 70 5.0 SN2 T ROBL

Product Category : WASHING MACHINE

Defective Product Code : 52141601SD00395 WSAXIS DX 70 5.0 SN2 T ROBL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230900395SW00074

Invoice No : 16054261

Invoice Date : 28/12/2023

DOP : 28/12/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Mfg Plant / Bhiwandi to Branch

Damaged Part(Only For Appl) : Cabinet

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 1000 Labour Rs. 200 (Includes gas charging, if any)

Nature Of Problem : Not\_repairable

Job Code Desc : CABINET#CABINET - PAINT SCRATCHED#APPLIANCE TO BE REPLACED

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : AB COOLING SOLUTIONS AB COOLING SOLUTIONS

Address : AB COOLING SOLUTIONS AB COOLING SOLUTIONS NO10 KRISHNA SWAMI ST; MUNILISPLE COLONY ; VEERAPPANCHATRAM, ERODE

City: VEERAPPANCHATRAM S.O

Telephone Number : 8610131309

Mobile Number : 9842241641

Observation text: DAMAGED CASE,DEALER STOCKSET COMPLAINT.CABINET BOTTOM BULGED AND DENT. STOCK AVAILABLE FOR RC PLEASE APPROVE THE SAME SIR.

Approval remark: CABINET DAMAGED -TRANSIT/HANDLING DAMAGES.

Sanction text: Cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.