

Dear NMS/SRINIR

Sanction No. SS4/C/100014 dated 15/12/2023 has been generated in reference to Service order No. 355991 dated 08/12/2023.

Area : SS4 COIMBATORE

Model : 40101723SD00069 /TEC QUBE 30L HS Q103 BLACK

Replacement Product Code : 40101723SD00069 TEC QUBE 30L HS Q103 BLACK

Product Category : CHOTUKOOL

Defective Product Code : 40101723SD00069 TEC QUBE 30L HS Q103 BLACK

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 2305000069TR00759

Invoice No : 159753

Invoice Date : 15/06/2023

DOP : 15/06/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Customer_Expectations_-_Not_allowing_Repairs

Job Code Desc : FUNCTIONAL#OUTER FAN#APPLIANCE REPLACED

PRA submitted by : AVUDAIAPPAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : RAKESH SAMANTHA

Address : RAKESH SAMANTHA PUNE RAJAPURAM SECOND STATE GANDHI PARK COIMBATORE

City: PONNAIYA RAJAPURAM

Telephone Number : 9930566947

Mobile Number : 9930566947

Observation text: NO COOLING- ENGINE ASSEMBLY REPLACED ONCE CUST WANTS REPLACEMENT DOP 15.06.2023 FG REPLACEMENT- CUSTOMER

Approval remark: NO COOLING-REPEAT-CUST CASE.

Sanction text: Approved as a special case stock is available

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.