

Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/108634 dated 31/01/2024 has been generated in reference to Service order No. 370735 dated 20/01/2024.

Area : SS4 COIMBATORE

Model : 52141501SD02733/RD EDGE 215C TAI FL BL

Replacement Product Code : 52141501SD02733 RD EDGE 215C TAI FL BL

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02733 RD EDGE 215C TAI FL BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230202733DR00238

Invoice No : 11135699

Invoice Date : 26/09/2023

DOP : 26/09/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) :

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 400 Labour Rs. 200 (Includes gas charging , if any)

Nature Of Problem : Not\_repairable

Job Code Desc : CABINET#CONDENSER CLAMP BROKEN#APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VIJAYALAKSHNI METAL&FUR MART

Address : VIJAYALAKSHNI METAL&FUR MART VIJAYALAKSHNI METAL&FUR MART, MAIN ROAD, BALASAMUDRAM,, THOTTIYAM,, TRICHY--622001

City: BALASAMUDRAM

Telephone Number : 9894654505

Mobile Number : 9894654505

Observation text: Condenser clamp broken Non repairable Appliance to be replaced

Approval remark: CONDENSER CLAMP BROKEN- NON REPAIRABLE

Sanction text: Approved as a special case

Kindly take necessary action.

ADHI

Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/108634 dated 31/01/2024 has been generated in reference to Service order No. 370735 dated 20/01/2024.

Area : SS4 COIMBATORE

Model : 52141501SD02733/RD EDGE 215C TAI FL BL

Replacement Product Code : 52141501SD02733 RD EDGE 215C TAI FL BL

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02733 RD EDGE 215C TAI FL BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230202733DR00238

Invoice No : 11135699

Invoice Date : 26/09/2023

DOP : 26/09/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) :

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 400 Labour Rs. 200 (Includes gas charging , if any)

Nature Of Problem : Not\_repairable

Job Code Desc : CABINET#CONDENSER CLAMP BROKEN#APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VIJAYALAKSHNI METAL&FUR MART

Address : VIJAYALAKSHNI METAL&FUR MART VIJAYALAKSHNI METAL&FUR MART, MAIN ROAD, BALASAMUDRAM,, THOTTIYAM,, TRICHY--622001

City: BALASAMUDRAM

Telephone Number : 9894654505

Mobile Number : 9894654505

Observation text: Condenser clamp broken Non repairable Appliance to be replaced  
Approval remark: CONDENSER CLAMP BROKEN- NON REPAIRABLE  
Sanction text: Approved as a special case

Kindly take necessary action.  
ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.