

Dear KHANGAN/ADHI

Sanction No. SS4/R/108748 dated 17/02/2024 has been generated in reference to Service order No. 376693 dated 07/02/2024.

Area : SS4 COIMBATORE

Model : 52141501SD02869/RD EMARVEL 207C THF AT BL

Replacement Product Code : 52141501SD02869 RD EMARVEL 207C THF AT BL

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02869 RD EMARVEL 207C THF AT BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230302869DR00492

Invoice No : 11124707

Invoice Date : 29/03/2023

DOP : 29/03/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

Nature Of Problem : Dealer\_replaced\_to\_customer\_approved\_by\_Service

Job Code Desc : SEALED SYSTEM#GAS LEAK - CONDENSOR#APPLIANCE TO BE REPLACED

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SRI AMMAN ELECTRONICS

Address : SRI AMMAN ELECTRONICS 142;MAIN RD; VINAYAKAPURAM; AATHUR;SALEM;

City: Narasingapuram

Telephone Number : 9442562555

Mobile Number : 8056821684

Observation text: CUSTOMER CASE- CONDENSOR RUST & LEAK AT CONDENSOR DEARER REPLACED TO CUSTOMER, STCK AVL FOR RC-CUS DOP-29/06/2023. CUS not allowed to repair sir.

Approval remark: CONDENSER RUST AND LEAK CASE-DOP 29/6/23 CUST NOT ACCEPTING REPAIR. REPLACED THRU DEALER.

Sanction text: Condenser problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.