Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/108648 dated 31/01/2024 has been generated in reference to Service order No. 374098 dated 30/01/2024.

Area: SS4 COIMBATORE

Model: 52141501SD02851/RD EMARVEL 207B TDF FS ST

Replacement Product Code : 52141501SD02851 RD EMARVEL 207B TDF FS ST ****** Replacement from Category Stock ******

Product Category : REFRIGERATOR

Defective Product Code: 52141501SD02851 RD EMARVEL 207B TDF FS ST Cabinet No(For Appl) and SO/RPL/Invoice No(For Others): 231002851DR02319

Invoice No : 11138613
Invoice Date : 27/11/2023

DOP : 27/11/2023

DEALER / CUSTOMER : DEALER Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : SidePanel

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 600 Labour Rs. 200 (Includes gas charging , if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL REAR

BOTTOM BUKCLING#APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & CO VASANTH & CO

Address: VASANTH & CO VASANTH & CO NO 2/2D1 FORT STATION ROAD TEPPAKULAM, TIRUCHIRAPPALLI,

City: Teppakulam

Telephone Number: 9940540045 Mobile Number: 9940540045

Observation text: Side panel bottom damaged Top 150 dealer policy - Carton b

ox attached Appliance to be replaced

Approval remark: SIDE PANEL DENT-TRANSIT/HANDLING DAMAGES. NOT FEASIBLE TO R

EPAIR. TOP 150 VASANTH & CO.

Sanction text: Top 150 dealer damaged policy case

Kindly take necessary action. ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.