Dear KHANGAN/ADHI

Sanction No. SS4/A/100959 dated 10/02/2024 has been generated in reference to Service order No. 616737 dated 29/01/2024.

Area: SS4 COIMBATORE

Model : 40101701SD01254/SIC 12TTC3-WWA SPLIT 3S

Replacement Product Code: 40101701SD01254 SIC 12TTC3-WWA SPLIT 3S

Product Category : AIR CONDITIONER

Defective Product Code: 40101701SD01254 SIC 12TTC3-WWA SPLIT 3S

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230200008SA03411

Invoice No : 11055587
Invoice Date : 22/04/2023

DOP : 22/04/2023

DEALER / CUSTOMER : CUSTOMER
Damage/Defective : Defective

AC UNIT : IDU-ODU

ODU No : 2302000080D00198

Nature Of Problem : Customer_Expectations_-_Not_allowing_Repairs Job Code Desc : PRODUCT PACKING#BOTTOM THERMOCOL#ESTIMATE GIVEN

PRA submitted by : Marudhudurai R Customer / Dealer Code : 40000E

Customer / Dealer Name : SREE AYYAN SREE AYYAN

Address: SREE AYYAN SREE AYYAN SAMUTHAIYAM PALAIYAKOTTAI MANNARGUDI THIRUV

ARUR DIS

City: Kumbakonam City

Telephone Number: 8072153729 Mobile Number: 9487088152

Observation text: Gas leak at ODU condenser - 22-4-23 cust not allowing to r

epair appliance to be replaced

Approval remark: GAS LEAK - CUST CASE- NOT ACCEPTING REPAIR.

Sanction text: Gas leak problem in the machine

Kindly take necessary action. ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective servic e executive.