

Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/108869 dated 12/03/2024 has been generated in reference to Service order No. 384682 dated 03/03/2024.

Area : SS4 COIMBATORE

Model : 52141501SD02864/RD EMARVEL 207C TDF AT BL

Replacement Product Code : 52141501SD02864 RD EMARVEL 207C TDF AT BL

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02864 RD EMARVEL 207C TDF AT BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 231102864DR00157

Invoice No : 11140480

Invoice Date : 10/01/2024

DOP : 10/01/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : SidePanel

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 600 Labour Rs. 300 (Includes gas charging , if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL DENT# APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : GIRIAS INVESTMENT PVT LTD GIRIAS INVESTMENT PVT LT

Address : GIRIAS INVESTMENT PVT LTD GIRIAS INVESTMENT PVT LTD 23;KARUR;BYPAS S MAIN ROAD; ANNAMALAI NAGAR , TIRUCHIRAPPALLI DT

City: Thillai Nagar S.O

Telephone Number : 8939970734

Mobile Number : 8939970734

Observation text: Side panel bottom scratches Top 150 dealer policy Appl
iance to be replaced

Approval remark: SIDE PANEL SCRATCHES- GIRIAS

Sanction text: Top 150 dealer damaged policy case

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.