

Dear KHANGAN/ADHI

Sanction No. SS4/R/108985 dated 27/03/2024 has been generated in reference to Service order No. 391282 dated 22/03/2024.

Area : SS4 COIMBATORE

Model : 52141501SD03151/RD EDGE 205A THF GL WN

Replacement Product Code : 52141501SD03151 RD EDGE 205A THF GL WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03151 RD EDGE 205A THF GL WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240103151DR04013

Invoice No : 11142315

Invoice Date : 14/02/2024

DOP : 14/02/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

Nature Of Problem : Dealer_replaced_to_customer_approved_by_Service

Job Code Desc : SEALED SYSTEM#GAS LEAK - UNABLE TO IDENTIFY#APPLIANCE TO BE REPLACED

PRA submitted by : Kumaraselvan R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SURIYA & CO SURIYA & CO

Address : SURIYA & CO SURIYA & CO BUS STAND MAIN RD, SURANDAI TIRUNELVELI,

City: Surandai S.O

Telephone Number : 9944393988

Mobile Number : 9788590927

Observation text: Gas leak, Cust ret to dlr due to not ok for repair Pls app r RC from FG as per dlr policy, Stk avl Cust DOP: 10.03.24

Approval remark: GAS LEAK-CUST CASE- NEW MACHINE REPLACED THRU DEALER.

Sanction text: gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.