

Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/109073 dated 13/04/2024 has been generated in reference to Service order No. 395996 dated 06/04/2024.

Area : SS4 COIMBATORE

Model : 52141501SD03255/RD ERIOPLS 205B THF SS WN

Replacement Product Code : 52141501SD03255 RD ERIOPLS 205B THF SS WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03255 RD ERIOPLS 205B THF SS WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240303255DR01212

Invoice No : 11145361

Invoice Date : 28/03/2024

DOP : 28/03/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : SidePanel

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 400 Labour Rs. 200 (Includes gas charging , if any)

Nature Of Problem : Top\_Dealer\_Trade\_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL REAR BOTTOM BUKCLING#APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & CO VASANTH & CO

Address : VASANTH & CO VASANTH & CO 20D/2D POST STATION ROAD, TRICHY DST

City: TEPPAKULAM

Telephone Number : 9500811877

Mobile Number : 9500811877

Observation text: Side panel bottom damaged Top 150 dealer policy Appliance to be replaced

Approval remark: SIDE PANEL DENT-TRANSIT/HANDLING DAMAGES.

Sanction text: cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.