

Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/109169 dated 30/04/2024 has been generated in reference to Service order No. 403279 dated 29/04/2024.

Area : SS4 COIMBATORE

Model : 52141501SD01942/RX EDGEPRO 225C 33 SL BS

Replacement Product Code : 52141501SD01942 RX EDGEPRO 225C 33 SL BS

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD01942 RX EDGEPRO 225C 33 SL BS

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 221001942DR00351

Invoice No : 11006007

Invoice Date : 31/01/2024

DOP : 31/01/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) :

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 3500 Labour Rs. 600 (Includes gas charging, if any)

Nature Of Problem : Not_repairable

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL REAR BOTTOM BUCKLING#APPLIANCE TO BE REPLACED

PRA submitted by : AVUDAIAPPAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : NEWEMBEROR ELECONLSC NEWEMBEROR ELECONLSC

Address : NEWEMBEROR ELECONLSC NEWEMBEROR ELECONLSC AVINASI ROAD ;PUSPA THEATER;

City: Tirupur North S.O

Telephone Number : 9865999339

Mobile Number : 9366686006

Observation text: BOTTOM BUCKLING CASE- NOT REPAIRABLE ASP WANTS REPLACEMENT
DOP 31.01.2024 FG REPLACEMENT

Approval remark: CABINET DAMAGED FROM THE BASE-TRANSIT/HANDLING DAMAGES.

Sanction text: Cabinet damaged in the game

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.