

Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/109181 dated 07/05/2024 has been generated in reference to Service order No. 397956 dated 12/04/2024.

Area : SS4 COIMBATORE

Model : 52141501SD03476/RD ERIOPLS 205A THF SS BL

Replacement Product Code : 52141501SD03476 RD ERIOPLS 205A THF SS BL

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03476 RD ERIOPLS 205A THF SS BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240203476DR07956

Invoice No : 11144137

Invoice Date : 12/03/2024

DOP : 12/03/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Dealer / Retailer to Customer

Damaged Part(Only For Appl) : Cabinet,SidePanel

Accountable By : Dealer

Estimate Cost To Repair : Spares Rs. 5000 Labour Rs. 500 (Includes gas charging, if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL REAR BOTTOM BUCKLING#APPLIANCE TO BE REPLACED

PRA submitted by : Kumaraselvan R

Customer / Dealer Code : 40000E

Customer / Dealer Name : ABISHA AGENCIES ABISHA AGENCIES

Address : ABISHA AGENCIES ABISHA AGENCIES NO ; 5 207 A2 SANKARA KOVIL ROAD AZHAGIYA PANDIPURAM

City: Kattarankulam B.O

Telephone Number : 9442725946

Mobile Number : 9443486107

Observation text: Erioplus leg buckling, Repair not possible Pls appr replacement from FG, Stk avl DOP: 12.03.24

Approval remark: SIDE PANEL BUCKLING- TRANSIT/HANDLING DAMAGES

Sanction text: cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.