

Dear KHANGAN/ADHI

Sanction No. SS4/A/101032 dated 11/05/2024 has been generated in reference to Service order No. 853796 dated 23/04/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01277/SIC 18TTC3 GWD SPLIT

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01277 SIC 18TTC3 GWD SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240101277SA04007DZ

Invoice No : 11142777

Invoice Date : 22/02/2024

DOP : 22/02/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Hiteshwaran G

Customer / Dealer Code : 40000E

Customer / Dealer Name : SAMU ELECTRONICS SAMU ELECTRONICS

Address : SAMU ELECTRONICS SAMU ELECTRONICS NO:12, SARANGABANI SANNATHI STREET, KOMBAKONAM

City: Kombakonam

Telephone Number : 9345968198

Mobile Number : 9500240862

Observation text: Compressor sealed system - gas leak issue Dealer replaced to customer on approval SRN due to stock unavailability

Approval remark: GAS LEAK-CUST CASE-NOT ACCEPTING REPAIR. REPLACED THRU DEALER.

Sanction text: compressor problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.