

Dear KHANGAN/ADHI

Sanction No. SS4/A/101039 dated 18/05/2024 has been generated in reference to Service order No. 182396 dated 14/05/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01140/SIC 18DTC3-WWA SPLIT

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01140 SIC 18DTC3-WWA SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240101140SA03397ZI

Invoice No : 11144590

Invoice Date : 18/03/2024

DOP : 18/03/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Hiteshwaran G

Customer / Dealer Code : 40000E

Customer / Dealer Name : DARLING PVC ELECTRONICS DARLING PVC ELECTRONICS

Address : DARLING PVC ELECTRONICS DARLING PVC ELECTRONICS NO:91 PERIYA KADAI
THERU MANNARKUDI THIRUVARUR

City: Kumbakonam Bazar

Telephone Number : 8610022671

Mobile Number : 8610022671

Observation text: Compressor Gas leak - sealed system Dealer replaced to customer on approval - 07.05.24 SRN due to stock unavailability

Approval remark: GAS LEAK - CUST CASE-NEW MACHINE. CUST NOT ACCEPTING REPAIR . REPLACED THRU DEALER.

Sanction text: gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.