

Dear KHANGAN/ADHI

Sanction No. SS4/A/101041 dated 23/05/2024 has been generated in reference to Service order No. 180937 dated 09/05/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01277/SIC 18TTC3 GWD SPLIT

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01277 SIC 18TTC3 GWD SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240101277SA05251CI

Invoice No : 11142844

Invoice Date : 24/02/2024

DOP : 24/02/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : AVUDAIAPPAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : CHINNASAMY SS FURNITURE CHINNASAMY SS FURNITURE

Address : CHINNASAMY SS FURNITURE CHINNASAMY SS FURNITURE NO;4 ANNUR ROAD T

ATA MOTOR OPP SIDE METTUPALAYAM POST COIMBATORE

City: Mettupalayam Bazaar

Telephone Number : 9597781907

Mobile Number : 8220766926

Observation text: fan motor jammed- dealer replaced to customer dealer wants replacement dop 03.04.2024 SRN DUE TO STOCK UNAVAILABILITY

Approval remark: FAN MOTOR DEFECT-CUST CASE-NOT ACCEPTING REPAIR REPLACED THRU DEALER.

Sanction text: Fan Motor problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.