

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/W/102228 dated 27/05/2024 has been generated in reference to Service order No. 409287 dated 17/05/2024.

Area : SS4 COIMBATORE

Model : 52141601SD00454/WFEON CEL 8014 IEBDT SLSR

Replacement Product Code : 52141601SD00454 WFEON CEL 8014 IEBDT SLSR

Product Category : WASHING MACHINE

Defective Product Code : 52141601SD00454 WFEON CEL 8014 IEBDT SLSR

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230900454FW00333

Invoice No : 11146137

Invoice Date : 16/04/2024

DOP : 16/04/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : Cabinet

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 600 Labour Rs. 300 (Includes gas charging , if any)

Nature Of Problem : Dealer_Expectations_-_Not_allowing_Repairs

Job Code Desc : CABINET#CABINET - BROKEN / SCRATCHY - TRANSIT DAMAGE#APPLIANCE TO BE REPLACED

PRA submitted by : Hiteshwaran G

Customer / Dealer Code : 40000E

Customer / Dealer Name : VEMBU SONS ELECTRONICS VEMBU SONS ELECTRONICS

Address : VEMBU SONS ELECTRONICS VEMBU SONS ELECTRONICS NO 49; MADURAI ROAD; CONTONMENT ; TRICHY;

City: Bheema Nagar

Telephone Number : 9865458282

Mobile Number : 9865458282

Observation text: Cabinet bottom damage scratch EBO needs replacement App liance to be replaced

Approval remark: CABINET DAMAGED FROM THE BASE-TRANSIT/HANDLING DAMAGES. EBO VEMBU SONS

Sanction text: cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.